



Hardware Compatibility Matrix NetVault: Backup 7.4.5 and Above Automated Tape Libraries

Cleaning Legend (Blank = not Supported)
 S = Standard Cleaning Only Supported
 G = Generic Cleaning Only Supported
 B = Both methods of Cleaning Supported which depends on manufacturer, see Application Notes for specifics

NOTE: NetVault supports the library and tape devices listed below on all operating systems that are supported by NetVault as either a backup server or SmartClient™ platform unless otherwise noted. Some device restrictions will be imposed by third party vendors for usages with their

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
Alacritus							
Alacritus	Nissho VTLA	FC	DLT7000	DLT IV	022C	N/A	ATL P1000 Library Emulation Mode Supported
			DLT8000	DLT IV		N/A	
Alacritus	Nissho VTLA AN300	FC	LTO-1	LTO-1	022C	N/A	ATL P1000 Library Emulation Mode Supported
			LTO-2	LTO-2			
Alacritus	Nissho VTLA 5000	FC	DLT8000	DLT IV	022C	N/A	ATL P1000 Library Emulation Mode Supported
			LTO-1	LTO-1			
			LTO-2	LTO-2			
			HP LTO-2	LTO-2			
Alacritus	Hitachi VF100	FC	DLT7000	DLT IV	022C	N/A	ATL P1000 Library Emulation Mode Supported
			DLT8000	DLT IV		N/A	
ATTO							
ATTO	Diamond Storage Array VT-Class	SCSI FC	ATTO Diamond Tape	Virtual	6.30 Build 022K	N/A	ATTO Diamond Storage Array is a disk subsystem emulating a virtual tape library and drives. See Application Notes for additional details.
BDT							
BDT	ThinStor Autoloader	SCSI	SDX-5xx	AIT-2	0200 0120 0110		
			SDX-7xx	AIT-3	0200 0120 0110		
			SDLT320	SDLT I	0200 0120 0110		
BDT	ThinStorPlus Autoloader	SCSI	LTO-1	LTO-1	0200 0120 0110		
			LTO-2	LTO-2	1.30		
			LTO-3	LTO-3	1.30		
BDT	FlexStor II	SCSI FC	SDLT600	SDLT II	1.20		Read Application Notes for special support conditions and cleaning details.
			LTO-2	LTO-2	0.60 / 1.65e	G	
BDT	FlexStor II-1U	SCSI	HP Ultrium 9xx	LTO-3	V1.00/1.70n		G
			HP Ultrium 3-SCSI	LTO-3			
Benchmark							
Benchmark	VS640	SCSI	VS Tape 80	VS-1	5032	S	
BreeceHill							
BreeceHill	Q2.15	SCSI	DLT7000	DLT III	1.71	S	
			DLT8000	DLT IV	1.71	S	
			SDLT	SDLT I	0001	N/A	
BreeceHill	Q7	SCSI	DLT4000	DLT III	4.53	S	
			DLT7000	DLT IV	0001	S	
BreeceHill	Q16	SCSI	LTO-3	LTO-3	0001	S	
BreeceHill	Q40	SCSI	LTO-3	LTO-3	0004	S	
BreeceHill	Q47	SCSI	DLT4000	DLT IV	4.53	S	
			DLT7000	DLT IV	0001	S	
BreeceHill	4.30	SCSI	DLT7000	DLT IV	4.04	S	
			DLT8000	DLT IV	4.04	S	
			SDLT	SDLT I	0001	N/A	
BreeceHill	4.50	SCSI	LTO-1	LTO-1	0001		
			DLT7000	DLT IV	4.04	S	
			DLT8000	DLT IV	4.04	S	
BreeceHill	6.100	SCSI	SDLT	SDLT I	0001	N/A	
			LTO-1	LTO-1	0001		
			DLT7000	DLT IV	4.04	S	
BreeceHill			DLT8000	DLT IV	4.04	S	
			SDLT	SDLT I	0001	N/A	
BreeceHill			LTO-1	LTO-1	0001		
			SDX-3xx	AIT-1	0001		

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
BreeceHill	8 PAK	SCSI	SDX-5xx	AIT-2	1.71		
			SDX-7xx	AIT-3	1.71		
BreeceHill	10 PAK	SCSI	SDLT	SDLT I	1.25	G	Read Application Note for SDLT cleaning details
			LTO-1	LTO-1			
			LTO-2	LTO-2			
			SDZ-1xx	SAIT-1		G	
BreeceHill	16 PAK	SCSI	SDX-3xx	AIT-1	0001		
			SDX-5xx	AIT-2	0001		
			SDX-7xx	AIT-3	0001		
Certance / Seagate							
Certance (Seagate RSS)	DDS4 Autoloader	SCSI	DDS4	DDS-4	8110		
Certance (Seagate RSS)	DAT432 Autoloader	SCSI	DAT72	DAT-72	A060	S	Read Application Note for cleaning details
Certance (Seagate RSS)	CLL1600	SCSI	LTO-1	LTO-1	S13.r		
Certance (Seagate RSS)	CLL6400	SCSI	LTO-3	LTO-3	V11x	G	Generic – requires cleaning slots and/or barcode prefix
Certance (Seagate RSS)	CLL3200 / Ultrium 2 Autoloader / LTO2 Autoloader	SCSI	LTO-2	LTO-2	S40.r	S	Read Application Note for cleaning details
Certance (Seagate RSS)	Viper 2000	SCSI	LTO-1	LTO-1	1.17		
Certance (Seagate RSS)	CP3100	SCSI	DAT72	DAT-72	A06B	N/A	Disk based tape emulation of DAT432 Autoloader.
Seagate RSS (Certance)	DDS4 Autoloader	SCSI	DDS4	DDS-4	8110		
Seagate RSS (Certance)	DAT432 Autoloader	SCSI	DAT72	DAT-72	A060	S	Read Application Note for cleaning details
Seagate RSS (Certance)	CLL1600	SCSI	LTO-1	LTO-1	S13.r		
Seagate RSS (Certance)	CLL3200 / Ultrium 2 Autoloader / LTO2 Autoloader	SCSI	LTO-2	LTO-2	S40.r	S	Read Application Note for cleaning details
Seagate RSS (Certance)	Viper 2000	SCSI	LTO-1	LTO-1	1.17		
Seagate RSS (Certance)	CP3100	SCSI	DAT72	DAT-72	A06B	N/A	Disk based tape emulation of DAT432 Autoloader.
Copan							
Copan	Copan Systems Revolution 200T	FC	Various See App Notes	Various See App Notes	3.00 Build 1069	N/A	Copan Systems Revolution 200T are disk subsystems emulating virtual tape libraries with a variety of supported drive and media types. See Application Notes for library and drive emulation modes supported.
Data Domain							
Data Domain	DD400 Enterprise Series VTL	FC	Various See App Notes	Various See App Notes	3.2.2.4-24897	N/A	The Data Domain DD410 emulates the STK L180 with IBM LTO-1 drives and LTO media. See Application Notes for library and drive emulation modes supported.
Dell							
Dell	PowerVault 120T	SCSI	DDS4	DDS-4	L0u6	S	
Dell	PowerVault 122T	SCSI	IBM Ultrium 1	LTO-1	D34R	G	
			IBM 3580-TD1	LTO-2	K17R	S	
			DLT VS80	DLT IV	5032	S	
			LTO-2	LTO-2		S	
Dell	PowerVault 124T	SCSI	LTO-3	LTO-3	0008	S	Read Application Note for cleaning details
			LTO-3	LTO-3		S	
			DLT VS160	DLT VS1		G	
Dell	PowerVault 132T	SCSI *FC	IBM Ultrium 1	LTO-1	105D - SCSI	S	Read Application Note for SDLT 320 cleaning details
			IBM 3580-TD1	LTO-2	*V310A.GY005 - FC	S	
			LTO-2	LTO-2	105D - SCSI	S	
			LTO-3	LTO-3	*V310A.GY005 - FC	S	
			SDLT320	SDLT I	227D - SCSI	S	
Dell	PowerVault 136T	SCSI FC	SDLT	SDLT I	3.03	S	Read Application Note for LTO-2 cleaning details
			LTO-2	LTO-2			
			LTO-3	LTO-3			
Dell	PowerVault ML6000	SCSI FC	LTO-3	LTO-3	200G.GS005	S	Uses ADIC i500 Template
			IBM Ultrium 4	LTO-4	400G.GS010	S	
Dell	PowerVault TL2000	SCSI	IBM Ultrium 3	LTO-3	0.80 / 170.e		See IBM TS3100 / TS3200 Application Notes for Details.
Dell	PowerVault TL4000	SCSI	IBM Ultrium 3	LTO-3	0.80 / 170.e		
DSM							

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
DSM	Terastore TL Series	SCSI	Mammoth-2	8MM	3.2.18		
			SDX-7xx	AIT-3	3.2.18		
			LTO-1	LTO-1	3.2.18		
EMC							
EMC	NDMP2D Feature	NDMP	Various See App Notes	Various See App Notes	DART OS 5.4 or higher	N/A	Requires NDMP Plugin Version 6.302 or higher. The NDMP2D Feature provides virtual tape support for the Celerra Disk Sub-systems. Use Template Files emcvd00.npk and emcvl00.npk to enable support.
EMC CDL	DL-210 DL-300 DL-700	FC	Various See App Notes	Various See App Notes	1.2 Build 1061	N/A	EMC Clarion Disk Library DL-Series are disk subsystems emulating virtual tape libraries with a variety of supported drive and media types. See Application Notes for library and drive emulation modes supported.
EMC CDL	DL4000 DL4100 DL4200	FC	Various See App Notes	Various See App Notes	3.0 (Build 1441)	N/A	EMC Clarion Disk Library DL-Series are disk subsystems emulating virtual tape libraries with a variety of supported drive and media types. See Application Notes for library and drive emulation modes supported.
FalconStor							
FalconStor	IPStor Virtual Tape Library	FC	Various See App Notes	Various See App Notes	3.0 Build 1047	N/A	IPStor Virtual Disk Library is a software product emulating virtual tape libraries with a variety of supported drive and media types. See Application Notes for library and drive emulation modes supported.
Fujitsu Siemens							
Fujitsu Siemens	Scalar 100	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	TBD		
		SCSI	LTO-2	LTO-2	TBD		
		SCSI	SDX-5xx	AIT-2	TBD		
		SCSI	SDX-7xx	AIT-3	TBD		
		SCSI	DLT7000	DLT IV	TBD		
		SCSI	DLT8000	DLT IV	TBD		
Fujitsu Siemens	ETERNUS LT130	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	0416	S	
		SCSI FC	LTO-2	LTO-2	0416	S	
		SCSI FC	LTO-3	LTO-3	0512	G	
Fujitsu Siemens	ETERNUS LT160	SCSI FC	LTO-1 LTO-2	LTO-1 LTO-2	0109	S	
Fujitsu Siemens	ETERNUS LT230	SCSI FC	LTO-3	LTO-3	0001 - FC 0004 - SCSI	S	Uses NEC T40A(2) Template and Application Notes.
Fujitsu Siemens	ETERNUS LT250	SCSI FC	IBM Ultrium 3 IBM 3580-TD3	LTO-3	1010	G	Read Application Notes for known issues and limitations.
		SCSI FC	HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	1010		
Fujitsu Siemens	ETERNUS LT270	FC	LTO-2 LTO-3	LTO-2 LTO-3	1020	G	
Fujitsu Siemens	PG-DTA103	SCSI FC	DAT-72	DAT-72	B410		Uses SW72x6 Template
Fujitsu Siemens	PG-LTL201	SCSI FC	LTO-2	LTO-2	0002	S	Uses Necltold Template
Fujitsu Siemens	PG-LT220	SCSI	LTO-3	LTO-3	0001	S	Uses NEC T16A Template
Fujitsu Siemens	FibreCAT TX24	SCSI	LTO-2	LTO-2	C113		Refer to Tandberg / Exabyte 224 Application Notes
		SCSI	IBM Ultrium 4 IBM 3580-TD4	LTO-4	74H6		Refer to Tandberg / Exabyte 448 Application Notes
Fujitsu Siemens	FibreCAT TX48	SCSI	IBM Ultrium 2 IBM 3580-TD2	LTO-2	D009		Refer to Tandberg / Exabyte 448 Application Notes
			IBM Ultrium 3 IBM 3580-TD3	LTO-3			Refer to Tandberg / Exabyte 448 Application Notes
		SCSI	IBM Ultrium 4 IBM 3580-TD4	LTO-4	74H6		Refer to Tandberg / Exabyte 448 Application Notes
Gateway							
Gateway	E-824R SuperLoader3	SCSI FC	DLT-V4	DLT VS1	0032 (V32.0)	G	Read the Application Notes for the Quantum SuperLoader3 for special support conditions and cleaning details. Use Quantum SuperLoader 3 template.
Gateway	E-826R SuperLoader3	SCSI FC	Certance Ultrium 3	LTO-3	0032 (V32.0)	G	Read the Application Notes for the Quantum SuperLoader3 for special support conditions and cleaning details. Use Quantum SuperLoader 3 template.
Grau							
Grau	ITL-M Series ITL-250L	SCSI	SDX-5xx	AIT-2	1.7.7.22		
			SDX-7xx	AIT-3			
			SDZ-1xx	SAIT-1			

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
			LTO-2	LTO-2			
			LTO-3	LTO-3		S	
Hitachi							
Hitachi	4697-L700A	SCSI	LTO-2	LTO-2	3.08.01		
Hitachi	4697-L220RD	SCSI	LTO-2	LTO-2	2.15.03	S	
Hitachi	DL121-10	SCSI	GF-2050	DVD	Z019		
Hitachi	HT-4697-L700A	SCSI	LTO-3	LTO-3	3.09.00		
HP (Compaq)							
HP	Surestore 1/8	SCSI	HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	H33r	G	
			DLT VS80	DLT IV	482A	S	
HP	Surestore 1/8 G2	SCSI SAS	HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	1.10		Read Application Note for cleaning details
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	1.10	G	
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	1.10		
HP	Surestore 1/9	SCSI	DLT1	DLT I	TBD		S
			DLT8000	DLT IV	2260		
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	TBD		
HP	Surestore 418, 718, 818	SCSI	DLT4000	DLT IV	TBD	S	
			DLT7000	DLT IV	TBD	S	
			DLT8000	DLT IV	TBD	S	
HP	Surestore DAT24x6 C1557A	SCSI	C1557A	DDS-3	TBD		
HP	Surestore DAT40x6 C5713A	SCSI	C5713A	DDS-4	H312 H910	S	Note: Firmware level H307 does not support cleaning. Read Application Note for cleaning details
HP	Surestore DAT72x6 Q1529A	SCSI	Q1529A	DAT72	TBD	S	
HP StorageWorks	SSL1016	SCSI	DLT1	DLT I	000A		
			SDLT220	SDLT I	000A	G	
			SDLT320	SDLT I	000A	G	
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	H43R	G	
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	000A	S	
HP StorageWorks	35GB Autoloader	SCSI	SDX-3xx	AIT-1	1.17	G	Uses Sony Lib-81 Template
HP StorageWorks	1/8 Autoloader	SCSI	HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	H33R	G	
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	N12R	S	
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	1.46	S	
			DLT VS80	DLT IV	482A	S	
			SDLT320	SDLT I	F10r	G	
HP StorageWorks	DAT72x10 1U Autoloader	SCSI	DAT72	DAT-72	1.00 / 1.65n	G	Read Application Note for cleaning details
HP StorageWorks	MSL2024	SCSI FC* SAS	HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	1.70 / 1.30e	G	Read Application Note for cleaning details
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	1.70 / 1.30e	G	
			HP Ultrium 18xx HP Ultrium 4-SCSI	LTO-4	5.60	G	
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	4.04 / 1.52e	G	
HP StorageWorks	MSL4048	SCSI FC* SAS	HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	4.04 / 1.52e	G	Read Application Note for cleaning details
			HP Ultrium 18xx HP Ultrium 4-SCSI	LTO-4	5.60	G	
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	8.30	G	
HP StorageWorks	MSL8096	SCSI FC* SAS	HP Ultrium 18xx HP Ultrium 4-SCSI	LTO-4	8.30	G	
			SDLT320	SDLT			
HP StorageWorks	MSL5000 Series	SCSI FC*	HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	0404	S	Read Application Note for cleaning details

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:		
HP StorageWorks	MSL6000 Series	SCSI FC*	SDLT600*	SDLT II	5.13		Read Application Note for cleaning details *FW 2929 is not supported		
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	4.22	S			
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	0507	G			
			HP Ultrium 18xx HP Ultrium 4-SCSI	LTO-4	5.20	G			
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2		G			
HP StorageWorks	EML E-Series	FC	HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	1022 (5.73.00)	G	Read Application Note for cleaning details		
			HP Ultrium 18xx HP Ultrium 4-SCSI	LTO-4		G			
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2		S			
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3		G			
HP StorageWorks	ESL E-Series	FC	HP Ultrium 18xx HP Ultrium 4-SCSI	LTO-4	1.01	G	*FW 2929 is not supported		
			SDLT600*	SDLT II		G			
			SDLT320	SDLT I		G			
			Various See App Notes	Various See App Notes		1.0.12		N/A	The HP 6000VLS emulates virtual tape libraries with a variety of supported drives and media types. See Application Notes for library and drive emulation modes supported.
			ESL9198 DLX	SCSI FC*		DLT 40/80		DLT IV	
HP StorageWorks	ESL9198 SL	SCSI FC*	SDLT	SDLT I	3.20p5	G			
HP StorageWorks	ESL9326 D	SCSI FC*	DLT 35/70	DLT IV	3.20p5	S			
HP StorageWorks	ESL9326 DX	SCSI FC*	DLT 40/80	DLT IV	3.20p5	S			
HP StorageWorks	ESL9326 SL	SCSI FC*	SDLT	SDLT I	3.20p5	G			
HP StorageWorks	ESL9322	SCSI FC*	SDLT220	SDLT I	3.20p5	G			
			SDLT320	SDLT I		G			
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1		S			
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2		S			
			SDLT220	SDLT I		G			
HP StorageWorks	ESL9595	SCSI FC*	SDLT320	SDLT I	3.20p5	G			
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1		S			
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2		S			
			MSL5026 DLX	SCSI FC*		DLT 40/80		DLT IV	3.11
HP StorageWorks	MSL5026 S2	SCSI FC*	SDLT320	SDLT I	3.11	G			
HP StorageWorks	MSL5026 SL	SCSI FC*	SDLT220	SDLT I	3.11	G			
HP StorageWorks	MSL5052 SL	SCSI FC*	SDLT	SDLT I	3.11	G			
HP StorageWorks	SSL2020 TL	SCSI	SDX-5xx	AIT-2	4.15	S			
HP StorageWorks	TL891 DLX	SCSI	DLT 40/80	DLT IV	5.25	S			
HP StorageWorks	TL895 DLT	SCSI	DLT 35/70	DLT IV	2.40p2	S			
HP StorageWorks	VLS1000i	iSCSI	HP Ultrium 4xx HP Ultrium 2-SCSI	Virtual	2.6.0.226 / 1.1.0.319				
HP StorageWorks	D2D Backup System	iSCSI	HP Ultrium 4xx HP Ultrium 2-SCSI	Virtual	kn6C-001.231 (kn6C)				
* NOTE1: StorageWorks FC support requires optional Modular Data Router **NOTE2: Virtual Tape Drives Supported									
Compaq	ESL9198 DLX	SCSI FC**	DLT 40/80	DLT IV	3.20p5	S			

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
Compaq	ESL9198 SL	SCSI FC**	SDLT	SDLT I	3.20p5		
Compaq	ESL9326 D	SCSI FC**	DLT 35/70	DLT IV	3.20p5	S	
Compaq	ESL9326 DX	SCSI FC**	DLT 40/80	DLT IV	3.20p5	S	
Compaq	ESL9326 SL	SCSI FC**	SDLT	SDLT I	3.20p5		
Compaq	ESL9595 SL	SCSI FC**	SDLT	SDLT I	3.20p5		
Compaq	MSL5026 DLX	SCSI FC**	DLT 40/80	DLT IV	3.11	S	
Compaq	MSL5026 SL	SCSI FC**	SDLT	SDLT I	3.11		
Compaq	MSL5052 SL	SCSI FC**	SDLT	SDLT I	3.11		
Compaq	SSL2020 TL	SCSI	SDX-5xx	AIT-2	4.15	S	
Compaq	TL891 DLX	SCSI	DLT 40/80	DLT IV	5.25	S	
Compaq	TL895 DLT	SCSI	DLT 35/70	DLT IV	2.40p2	S	
** NOTE2: Compaq FC support requires optional Modular Data Router							
IBM							
IBM	Magstar 3590 B11/E11	SCSI	3590	IBM Linear	B88C		
IBM	3590H11	SCSI	3590	IBM Linear	F2D4	G	Read Application Note for cleaning details
IBM	3575	SCSI	3570C/A	IBM Linear	2.19		
IBM	3581	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	0001		
			IBM Ultrium 2 IBM 3580-TD2	LTO-2	1.60	S	
			IBM Ultrium 3 IBM 3580-TD3	LTO-3	0001	S	
IBM	3582	SCSI	IBM Ultrium 2 IBM 3580-TD2	LTO-2	217B	S	
		SCSI FC	IBM Ultrium 3 IBM 3580-TD3	LTO-3	307B		
IBM	3583	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	2.05.0003	S	Adaptec SCSI Driver version 6.4.630.100 is required on Windows 2000.
		SCSI FC	IBM Ultrium 2 IBM 3580-TD2	LTO-2	2.05.0003	S	
		SCSI FC	IBM Ultrium 3 IBM 3580-TD3	LTO-3	2.05.0003	S	
IBM	TS3500 (Formally 3584)	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	0BN1 v1200	S	
		FC	IBM Ultrium IBM 3580-TD2	LTO-2	v2140	S	
		FC	IBM Ultrium 3 IBM 3580-TD3	LTO-3	0001	S	
		FC	IBM 3592 TS1120	IBM Linear	0001		
IBM	3607	SCSI	SDLT	SDLT I	0015		
IBM	36232LX	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	0002	S	
			IBM Ultrium 2 IBM 3580-TD2	LTO-2	1.30	S	
IBM	36232SX	SCSI	SDLT-320	SDLT I	1.30		
IBM	360726X	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	000F	S	
IBM	4560SLX	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	2.21		
		FC	IBM Ultrium 2 IBM 3580-TD2	LTO-2			
IBM	TS3310 (3576)	SCSI FC	IBM Ultrium 3 IBM 3580-TD3	LTO-3	150G.GS002	S	Shared MailBox is not supported.

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
IBM	TS3100 (3573 L2U)	SCSI FC	IBM Ultrium 4 IBM 3580-TD4	LTO-4	400G.GS010	S	Shared MailBox is not supported.
IBM	TS3100 (3573 L2U)	SCSI FC	IBM Ultrium 3 IBM 3580-TD3	LTO-3	0.70 / 1.65e	S	
IBM	TS3200 (3573 L4U)	SCSI FC SAS	IBM Ultrium 3 IBM 3580-TD3	LTO-3	0.70 / 1.65e	S	SAS Interface support is currently only available with IBM Ultrium4 Tape Drives.
			IBM Ultrium 4 IBM 3580-TD4	LTO-4	4.40	S	
IBM	TS7510	FC	IBM Ultrium 2 IBM 3580-TD2	LTO-2	v1.10 Build 1143 Patch Level 114305	N/A	The IBM VE TS7510 is a system which emulates the IBM 3584 tape library with the IBM LTO-2, LTO-3 or 3592J1A tape drives. See Application Notes for special support conditions.
			IBM Ultrium 3 IBM 3580-TD3	LTO-3			
KEL							
KEL KANEMATSU ELECTRONICS LTD	EG-4500open	FC	IBM Ultrium 3 IBM 3580-TD3	LTO-3	v1.00 (Build 1317)	N/A	See Application Notes For Details.
Lynx Technologies	LX30	SCSI	LTO-1	LTO-1	4.04	S	Read Application Note for cleaning details. Use Compaq Template 'MSL5.TPL'.
			LTO-2	LTO-2			
Lynx Technologies	LX60	SCSI	LTO-1	LTO-1	4.21	S	Read Application Note for cleaning details. Use Compaq Template 'MSL5.TPL'.
			LTO-2	LTO-2			
Matsushita Kotobuki							
Matsushita Kotobuki	DDS Backup Library	SCSI	DDS-4	DDS-4	9A29		
Matsushita Kotobuki	DAT72 Library	SCSI	DAT72	DAT-72	BA03	G	
NEC							
NEC NEC Compact Autoloader	TL620 (DL0101H)	SCSI	TRAVAN	QIC	0001		
		SCSI	DLT8000	DLT IV	0002	S	
	LL0101H	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	0002	S	
		SCSI	IBM Ultrium 2 IBM 3580-TD2	LTO-2	0002	S	
		SCSI	IBM Ultrium 3 IBM 3580-TD3	LTO-3	0004	S	
		SCSI	HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	0004	G	
		SCSI	HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	0004	G	
		SCSI	IBM Ultrium 3 IBM 3580-TD3	LTO-3	0004	B	Read Application Notes for cleaning details.
(SL0101H)	SCSI	SDLT	SDLT I	0003	N/A		
NEC	iStorage T180	SCSI	Seagate Viper 200	LTO-1	0001		
			IBM Ultrium 1 IBM 3580-TD1	LTO-1	0001		
			LTO-2	LTO-2			
			LTO-3	LTO-3	0001		
NEC	iStorage T700	SCSI	LTO-1	LTO-1	0001		
			LTO-2	LTO-2	0001		
			LTO-3	LTO-3	0001		
			LTO-1	LTO-1	0001		
NEC	iStorage T40	SCSI	LTO-2	LTO-2	0001		
			LTO-3	LTO-3	0001		
			LTO-2	LTO-2	0001		
NEC	iStorage T40A	SCSI	LTO-2	LTO-2	0002	S	IBM and HP LTO-2 drives supported
		FC	LTO-3	LTO-3	0004	S	IBM and HP LTO-3 drives supported
NEC	iStorage T40A2	SCSI FC	LTO-3	LTO-3	0001	S	IBM and HP LTO-3 drives supported
NEC	iStorage T16A	SCSI	LTO-2	LTO-2	0001	S	IBM LTO-2 and IBM/HP LTO-3 drives supported
			LTO-3	LTO-3	0001	S	
NEC	iStorage T16A2	SAS	IBM Ultrium 3 IBM 3580-TD3	LTO-3	0001	G	
NEC	iStorage T80	SCSI	LTO-1	LTO-1	0001		
			LTO-2	LTO-2	0001		
			LTO-3	LTO-3	0001		
NEC	iStorage T5000VT Series	FC	DLT7000	DLT IV	02.28.27	N/A	Uses the Quantum DX-Series Template

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
NEC	T100A	SCSI	IBM Ultrium 3	LTO-3	1020	G	Refer to Fujitsu LT250 Application Notes For Details
		FC	IBM 3580-TD3	LTO-3			
NEC	T700A	SCSI	HP Ultrium 9xx	LTO-3	2037	G	Refer to Fujitsu LT270 Application Notes For Details
		FC	HP Ultrium 3-SCSI	LTO-3			
NetApp							
NetApp	NearStore VTL	FC iSCSI	Various See App Notes	Various See App Notes	0001		See App Notes for emulation modes supported.
Overland Storage							
Overland Storage	Loader-Xpress	SCSI	DLT4000	DLT III	0001	S	
			DLT1	DLT-1	0517	S	
			DLT7000	DLT IV	0001	S	
			DLT8000	DLT IV	0001	S	
			LTO-1	LTO-1	1.18		
			LTO-2	LTO-2	0001		
			LTO-3	LTO-3	1.07		
			SDLT	SDLT I	0001	N/A	
Overland Storage	PowerLoader	SCSI	AIT-1	AIT-1	4.17	S	
			DLT1	DLT-1	5.24	S	
			DLT8000	DLT IV	5.24	S	
			SDLT	SDLT I	1.04	N/A	
			LTO-1	LTO-1	v1.00		
			LTO-2	LTO-2	0001		
			LTO-3	LTO-3	v1.07		
			DLT4000	DLT III	0001	S	
Overland Storage	Library-Xpress	SCSI	DLT7000	DLT IV	0001	S	
			DLT8000	DLT IV	022B	S	
			SDLT	SDLT I	0001	N/A	
			DLT8000	DLT IV	2.21	S	
			IBM Ultrium 1	LTO-1	2.21	B	
			IBM 3580-TD1	LTO-1	2.21	B	
			HP Ultrium 4xx	LTO-2	2.21	S	
			HP Ultrium 2-SCSI	LTO-2	2.21	S	
Overland Storage	Neo Series 2000 / 4000	SCSI FC iSCSI	HP Ultrium 9xx	LTO-3	2.21	G	Note: iSCSI is supported on Windows Platform only, see application notes for details. Read Application Notes for cleaning details.
			HP Ultrium 3-SCSI	LTO-3	2.21	G	
			HP Ultrium 1840	LTO-4	6.02	G	
			HP Ultrium 4-SCSI	LTO-4	6.02	G	
			SDLT220	SDLT I	2.21		
			SDLT320	SDLT I	2.21		
			SDLT600	SDLT II	2.21	G	
			SDLT1600	SDLT II	1.x	G	
Overland Storage	Neo Series 8000	SCSI FC	HP Ultrium 4xx	LTO-2	1.x		
			HP Ultrium 2-SCSI	LTO-2	1.x		
			HP Ultrium 9xx	LTO-3	1.x	S	
			HP Ultrium 3-SCSI	LTO-3	1.x	S	
Overland Storage	REO 1000	iSCSI	HP Ultrium 4xx	Virtual	2.1.1.34	N/A	Configurable as either a disk sub-system for a NetVault Virtual Disk Library and/or a virtual tape library emulating HP LTO-2 devices. See application notes for details on supported configuration options.
	REO 4000	iSCSI FC	HP Ultrium 2-SCSI	Virtual			
	REO 4500	iSCSI FC	HP Ultrium 4xx	Virtual	4.0.2.31 (0425)		
	REO 9000	iSCSI FC	HP Ultrium 2-SCSI	Virtual	2.1.1.34		
Overland Storage	LibraryPro	SCSI	SDX-3xx	AIT-1	0001	S	
			SDX-5xx	AIT-2	0001	S	
			SDX-7xx	AIT-3	0001	S	
Overland Storage	ARCVault 12 / 24 / 48	SCSI	HP Ultrium 9xx	LTO-3	0153		See App Notes for details on Cleaning Tape Support
			HP Ultrium 1840	LTO-4			
Plasmon							

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
Plasmon	V10 (LTO 10.1)	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	2.4.5	S	
			IBM Ultrium 2 IBM 3580-TD2	LTO-2		S	
Plasmon	V15	SCSI	SDX-5xx	AIT-2	12.11.5		
			SDX-7xx	AIT-3	12.11.5		
Plasmon	V2 (LTO 21.2)	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	2.4.7	S	
			IBM Ultrium 2 IBM 3580-TD2	LTO-2		S	
Plasmon	V30	SCSI	SDX-5xx	AIT-2	12.11.5		
			SDX-7xx	AIT-3	12.11.5		
Plasmon	V40	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	1.04		
			IBM Ultrium 2 IBM 3580-TD2	LTO-2	1.06		
Plasmon	V60	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	1.04		
			IBM Ultrium 2 IBM 3580-TD2	LTO-2	1.06		
Plasmon	V68	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	1.04		
			IBM Ultrium 2 IBM 3580-TD2	LTO-2	1.06		
Plasmon	V102 (LTO 100.6)	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	1.03		
			IBM Ultrium 2 IBM 3580-TD2	LTO-2	1.06		
Plasmon	D-Series	SCSI	Matsushita SW-9571	DVD	1.17	N/A	Please see application note for support details
Qualstar							
Qualstar	TLS 4 series	SCSI	SDX-3xx	AIT-1	0001	S	
			SDX-5xx	AIT-2	2.09	S	
			SDX-7xx	AIT-3	2.09		
Qualstar	TLS 5 series	SCSI	SDZ-1xx	SAIT-1	0001		
Qualstar	TLS 6 series	SCSI	DLT 8000	DLT IV	0001	S	
			SDLT	SDLT I	0001	N/A	
			SDLT600	SDLT II	0001		
Qualstar	TLS 8 series	SCSI	HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	0001	S	
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	0001	S	
Qualstar	RLS Series	SCSI	SDX-5xx	AIT-2	0003		
			SDX-7xx	AIT-3	0003		
			SDLT320	SDLT I	0003		
			SDLT600	SDLT II	0003		
			SDZ-1xx	SAIT-1	0003		
			SDX-1100	AIT-5	0068		
Qualstar	XLS-8xxx	SCSI	IBM Ultrium 3 IBM 3580-TD3	LTO-3	0651	G	
Quantum / ADIC / ATL							
Quantum / ADIC / ATL	ADIC VX-450 ADIC VX-650	FC	Various See App Notes	Various See App Notes	1.1.0 Build21	N/A	Disk based emulation of tape library and drives. Only the Pathlight VX sign-on string is supported for library emulation, see Application Note for details.
Quantum / ADIC / ATL	ADIC AML/J	SCSI	LTO-1	LTO-1	3.12		Requires ADIC DAS client software and NetVault VaultShare for DAS plugin option. Contact sales representative for latest platform availability.
			SDX-5xx	AIT-2			
Quantum / ADIC / ATL	ADIC Scalar 24	SCSI *iSCSI **FC	IBM Ultrium 1 IBM 3580-TD1	LTO-1	003.0L3 **V237A.GZ001	S	* iSCSI support is Windows only using LTO-1 / LTO-2 drives, SNC 4501 iSCSI Bridge and Adaptec 7211 iSCSI Initiator and driver.
			IBM Ultrium 2 IBM 3580-TD2	LTO-2		S	
			IBM Ultrium 3 IBM 3580-TD3	LTO-3		S	
			SDLT320	SDLT I		S	
			SDLT600	SDLT II		S	

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
Quantum / ADIC / ATL	ADIC Scalar 100	SCSI iSCSI*	IBM Ultrium 1 IBM 3580-TD1	LTO-1	0001		Read Application Note for complete drive cleaning details. * iSCSI support is Windows only using LTO-1 / LTO-2 drives, SNC 4500 iSCSI Bridge and Adaptec 7211 iSCSI Initiator and driver.
			IBM Ultrium 2 IBM 3580-TD2	LTO-2	0001		
			IBM Ultrium 3 IBM 3580-TD3	LTO-3	6.02A		
			SDX-5xx	AIT-2	0001	S	
			SDX-7xx	AIT-3	0001		
			DLT7000	DLT IV	0001	S	
			DLT8000	DLT IV	0001	S	
			SDLT320	SDLT I	0001		
			SDLT600	SDLT II	0001		
			SDX-3xx	AIT-1	0001		
Quantum / ADIC / ATL	ADIC Scalar 210	SCSI	DLT7000	DLT IV	0106	S	
	ADIC Scalar 218	SCSI	DLT8000	DLT IV	0001	S	
Quantum / ADIC / ATL		ADIC Scalar 220	FC	DLT7000	DLT IV	0106	S
	DLT8000			DLT IV	0001	S	
Quantum / ADIC / ATL	ADIC Scalar 1000	SCSI	SDX-5xx	AIT-2	0001		
		SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	0001		
		SCSI	IBM Ultrium 2 IBM 3580-TD2	LTO-2	0001		
		SCSI	DLT7000	DLT IV	0001	S	
		SCSI	DLT8000	DLT IV	0001	S	
		SCSI	SDLT320	SDLT I	0001		
		SCSI	SDX-5xx	AIT-2	0001	S	
		SCSI	SDX-7xx	AIT-3	0001		
		SCSI	3590	IBM Linear	0001		
		Quantum / ADIC / ATL	ADIC Scalar 10K	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	
FC	IBM Ultrium 2 IBM 3580-TD2			LTO-2	200a.T0001		
SCSI	IBM Ultrium 3 IBM 3580-TD3			LTO-3	300a.T0001		
FC	IBM Ultrium 3 IBM 3580-TD3			LTO-3	300a.T0001		
SCSI	SDLT220			SDLT I	200a.T0001		
SCSI	SDLT320			SDLT I	200a.T0001		
SCSI	SDX-5xx			AIT-2	200a.T0001		
SCSI	SDX-7xx			AIT-3	200a.T0001		
SCSI	3590			IBM Linear	200a.T0001		
Quantum / ADIC / ATL	ADIC Scalar i2000	SCSI FC	IBM Ultrium 1 IBM 3580-TD1	LTO-1	400A	S	Requires new device template (SCI2004.npk)
			IBM Ultrium 2 IBM 3580-TD2	LTO-2			
			IBM Ultrium 3 IBM 3580-TD3	LTO-3			
			SDLT600	SDLT II			
			IBM Ultrium 2 IBM 3580-TD2	LTO-2			
Quantum / ADIC / ATL	ADIC Scalar i500	SCSI FC	IBM Ultrium 3 IBM 3580-TD3	LTO-3	0001		Shared Mailbox not supported.
			IBM Ultrium 4 IBM 3580-TD4	LTO-4	200G.GS005	S	
			SDLT320	SDLT I	400G.GS010	S	
Quantum / ADIC / ATL	ADIC FastStor2	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	F10r	G	Read Application Note for SDLT 320 cleaning details
			IBM Ultrium 2 IBM 3580-TD2	LTO-2			
Quantum / ADIC / ATL	ADIC FastStor7	SCSI	DLT4000	DLT III	0001	S	
			DLT7000	DLT IV	0001	S	
			DLT8000	DLT IV	0001	S	
			IBM Ultrium 1 IBM 3580-TD1	LTO-1	0001		
			DLT4000	DLT III	0001	S	

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
Quantum / ADIC / ATL	ADIC FastStor22	SCSI	DLT7000	DLT IV	0001	S	
			DLT8000	DLT IV	0001	S	
Quantum / ADIC / ATL	ATL SuperLoader 1280L	SCSI	DLT4000	DLT III	0001		
			DLT1	DLT I	V 13.0		
Quantum / ADIC / ATL	ATL SuperLoader 5120L	SCSI	HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	0006		
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	0006	S	
			SDLT320	SDLT I	V 13.0	G	
			SDLT600	SDLT II	0001		
Quantum / ADIC / ATL	SuperLoader3	SCSI FC	SDLT600	SDLT II		G	Read Application Notes for special support conditions and cleaning details.
			LTO-2	LTO-2		G	
			Quantum LTO3HH	LTO-3	000C	G	
			DLT-V4	VS-1		G	
			DLT-S4	VS-1		G	
			DLT VS160	VS-1		G	
			LTO-1	LTO-1			
Quantum / ADIC / ATL	ValueLoader	SCSI	LTO-2	LTO-2			
			SDLT320	SDLT I	3203 0130	S	
			DLT VS 80	VS-1			
			DLT VS 160	VS-1			
Quantum / ADIC / ATL	ATL M1500	SCSI	DLT8000	DLT IV	2.02	S	
			SDLT220	SDLT I	2.02		
			SDLT320	SDLT I	2.02		
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	2.02		
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	2.02		
			SDLT600	SDLT II	TBD		
Quantum / ADIC / ATL	ATL M1800	SCSI	DLT8000	DLT IV	2.10	S	Uses M1500 Library Template
			SDLT220	SDLT I	2.10		
			SDLT320	SDLT I	2.10		
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	2.10		
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	2.10		
Quantum / ADIC / ATL	ATL M2500	SCSI	DLT8000	DLT IV	2.02	S	
			SDLT220	SDLT I	2.02		
			SDLT320	SDLT I	2.02		
			LTO-1	LTO-1	2.02		
			LTO-2	LTO-2	2.02		
			LTO-2	LTO-2		S	
Quantum / ADIC / ATL	Quantum PX720	SCSI FC	LTO-3	LTO-3			Read Application Notes for special support conditions and cleaning details.
			SDLT320	SDLT I	1.10p	G	
			SDLT600	SDLT II		G	
			DLT-S4	VS-1		G	
			LTO-2	LTO-2		G	
Quantum / ADIC / ATL	Quantum PX500 Series	SCSI FC iSCSI	LTO-3	LTO-3			Read Application Notes for special support conditions and cleaning details. iSCSI interface support on Windows only.
			SDLT600	SDLT II	V14.0 (000E)	G	
			DLT-S4	VS-1		G	
			SDLT320	SDLT I	001A		
			Various See App Notes**	Various See App Notes	02.10.16	N/A	
			Various See App Notes**	Various See App Notes	02.10.16	N/A	
Quantum / ADIC / ATL	Quantum DX30 EBS	FC	Various See App Notes**	Various See App Notes	02.65.19	N/A	*Enhanced Backup Systems (EBS)* are disk subsystems emulating virtual tape libraries with DLT7000 drives. **See Application Notes for library emulation modes supported.
	Quantum DX100 EBS						
	Quantum DX3000	FC	Various See App Notes**	Various See App Notes	04.00.150 (DXi - 0400)	N/A	
	Quantum DXi 3500						

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
	Quantum DX5000	iSCSI	Various See App Notes**	Various See App Notes	02.65.19		
	Quantum DXi 5500		Various See App Notes**	Various See App Notes	04.00.150 (DXi - 0400)	N/A	
Quantum / ADIC / ATL	ATL P1000	SCSI	DLT4000	DLT III	0001	S	
			DLT7000	DLT IV	0001	S	
			DLT8000	DLT IV	0001	S	
			SDLT320	SDLT I	0001	N/A	
Quantum / ADIC / ATL	ATL 7100	SCSI	DLT7000	DLT IV	0001	S	
			DLT8000	DLT IV	0001	S	
			SDLT320	SDLT I	0001	N/A	
Quantum / ADIC / ATL	ATL P2000	SCSI FC	DLT7000	DLT IV	0001	S	
			DLT8000	DLT IV	0001	S	
			SDLT320	SDLT I	0001	N/A	
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	0001		
Quantum / ADIC / ATL	ATL P3000	SCSI FC	DLT7000	DLT IV	0001	S	
			DLT8000	DLT IV	0001	S	
			SDLT320	SDLT I	0001	N/A	
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	0001		
Quantum / ADIC / ATL	ATL P4000	SCSI FC	DLT8000	DLT IV	0001	S	
			SDLT320	SDLT I	0001	N/A	
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	0001		
			DLT7000	DLT IV	0001	S	
Quantum / ADIC / ATL	ATL P6000	SCSI FC	DLT8000	DLT IV	0001	S	
			DLT7000	DLT IV	0001	S	
			SDLT320	SDLT I	0001	N/A	
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	0001		
Quantum / ADIC / ATL	ATL P7000	SCSI FC	DLT8000	DLT IV	0001	S	
			SDLT320	SDLT I	0001	N/A	
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	0001		
			DLT7000	DLT IV	0001	S	
Sepaton							
Sepaton	S2100 ES2	SCSI FC	Various See App Notes	Various See App Notes	Various based on Library model See App Notes	N/A	The Sepaton S2100 Virtual Disk Library emulates virtual tape libraries with a variety of supported drives and media types. See Application Notes for firmware requirements and library and drive emulation modes supported.
Sony							
Sony	TSL-A300C	SCSI	SDX-300	AIT-1	0000		
Sony	TSL-A500C	SCSI	SDX-500	AIT-2	0000		
Sony	TSL-11000 Autoloader	SCSI	DDS-4	DDS-4	L0u6	S	
Sony	LIB-81	SCSI	SDX-3xx	AIT-1	0100	S	
			SDX-4xx	AIT-1	0100		
			SDX-5xx	AIT-2	0100		
			SDX-7xx	AIT-3	0106		
			SDX-8xx	AIT-3	0106		
			SDX-9xx	AIT-4	0106		
			SDX-11xx	AIT-5	0109		
Sony	LIB-D81	SCSI	SDX-3xx	AIT-1	0100	S	
			SDX-4xx	AIT-1	0100		
			SDX-5xx	AIT-2	0104		
			SDX-7xx	AIT-3	0104		
			SDX-8xx	AIT-3	0104		
			SDX-9xx	AIT-4	0104		
			SDX-11xx	AIT-5	0109		
Sony	LIB-152 / E	SCSI	SDX-3xx	AIT-1	1019	S	
			SDX-5xx	AIT-2	1019	S	
			SDX-7xx	AIT-3	1019		
			SDX-3xx	AIT-1	0102		
			SDX-4xx	AIT-1	0102		
			SDX-500	AIT-2	0102		

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:	
Sony	LIB-162	SCSI	SDX-700	AIT-3	0203	S	*AIT-3 Ex drives are supported with standard cleaning	
			SDX-800	AIT-3	0203			
			SDX-900	AIT-4	0203			
			SDX-1100	AIT-5	0206			
Sony	LIB-302	SCSI	SDX-3xx	AIT-1	S019	S		
			SDX-5xx	AIT-2	S019	S		
			SDX-7xx	AIT-3	S019			
Sony	LIB-304	SCSI	SDX-5xx	AIT-2	0001	S		
Sony	DMS-B9	SCSI	GY-2120	DTF-1	1.20			
Sony	DMS-B80L	SCSI	GY-8240	DTF-2	1.10			
Sony	DMS-B150L	SCSI	GY-8240	DTF-2	1.10			
Sony	CSM-200 BS/BF CSM-100 BS/BF CSM-60 BS/BF	SCSI FC	SDZ-1xx	SAIT-1	3.01	S		
			SDZ-2xx	SAIT-2				
			IBM Ultrium 3 IBM 3580-TD3	LTO-3	6.30			
			IBM Ultrium 4 IBM 3580-TD4	LTO-4				
Sony	CSM-20	SCSI FC	SDZ-1xx	SAIT-1	0102	G		
			SDZ-2xx	SAIT-2				
			IBM Ultrium 3 IBM 3580-TD3	LTO-3				
Spectra Logic								
Spectra Logic	Spectra 2K	SCSI FC	SDX-3xx	AIT-1	0001	S	Both iSCSI and NDMP are supported GBE protocols	
			SDX-5xx	AIT-2	0001	S		
			SDX-7xx	AIT-3	1020			
		SDX-9xx	AIT-4	0001				
		iSCSI NDMP	SDX-3xx	AIT-1	0001	S		
			SDX-5xx	AIT-2	0001			
SDX-7xx	AIT-3		1020					
Spectra Logic	Spectra 10K	SCSI FC	SDX-5xx	AIT-2	5.00.15	S		
Spectra Logic	Spectra 12K	SCSI FC	SDX-7xx	AIT-3	0001			
			SDX-9xx	AIT-4	0001			
			SDX-5xx	AIT-2	0126			
		NDMP	SDX-7xx	AIT-3	0001			
			SDX-9xx	AIT-4	0001			
			SDX-5xx	AIT-2	4.1.16			
Spectra Logic	Spectra 20K	SCSI FC	SDX-7xx	AIT-3	0126			
			SDX-9xx	AIT-4	0001			
			SDX-5xx	AIT-2	0001			
		NDMP	SDX-7xx	AIT-3	4.1.16			
			SDX-9xx	AIT-4	0001			
			SDX-5xx	AIT-2	0001			
Spectra Logic	Spectra 64K	SCSI FC	SDX-7xx	AIT-3	0001			
			SDX-9xx	AIT-4	0001			
			SDX-5xx	AIT-2	0126			
		NDMP	SDX-7xx	AIT-3	4.1.16			
			SDX-9xx	AIT-4	0001			
			SDX-5xx	AIT-2	0001			
Spectra Logic	Spectra T50/S50	SCSI FC	IBM Ultrium 2 / IBM 3580-TD2	LTO-2	2000 (BlueScale9.4.1-20060109F)	G	Read Application Note for cleaning details	
			IBM Ultrium 3 / IBM 3580-TD3	LTO-3				
			IBM Ultrium 4 IBM 3580-TD4	LTO-4		FW: 7.8.5 SW: BlueScale10.0-20070719F		S
			IBM Ultrium 2 / IBM 3580-TD2	LTO-2		Controller- 1.1.0.1 QIP- 5.0.0.18		S
Spectra Logic	Spectra T120	FC	IBM Ultrium 3 / IBM 3580-TD3	LTO-3	FW: 7.8.5 SW: BlueScale10.0-20070719F	S		
			IBM Ultrium 4 IBM 3580-TD4	LTO-4				
			SDZ-1xx	SAIT-1				

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
Spectra Logic	Spectra T950	FC	IBM Ultrium 2 IBM 3580-TD2	LTO-2	Controller- 1.1.0.1 QIP- 5.0.0.18	S	
			IBM Ultrium 3 IBM 3580-TD3	LTO-3	Controller- 1.1.0.1 QIP- 5.0.0.18	S	
			IBM Ultrium 4 IBM 3580-TD4	LTO-4	FW: 7.8.5 SW: BlueScale10.0-20070719F	S	
			SDLT600	SDLT II	Controller- 1.1.0.1 QIP- 5.0.0.18		
			SDZ-1xx	SAIT-1	Controller- 1.1.0.1 QIP- 5.0.0.18		
			RXT (LTO-2)	LTO-2	Controller- 1.1.0.1 QIP- 5.0.0.18	N/A	
SUN/STK							
SUN/STK	9310 PowerHorn	ACSLs APM	9840	SUN STK	ACSLs 6.0.1		
			9940	SUN STK			
			3592	IBM Linear			
SUN/STK	9710	SCSI ACSLs	DLT4000	DLT III	0001	S*	* For Non-ACSLs Environments
			DLT7000	DLT IV	0001	S*	
			DLT8000	DLT IV	0001	S*	
			9840	SUN STK	0001	S*	
SUN/STK	9730	SCSI ACSLs	DLT4000	DLT III	0001	S*	* For Non-ACSLs Environments
			DLT7000	DLT IV	0001	S*	
SUN/STK	9738 TimberWolf	ACSLs APM	9840	SUN STK	ACSLs 6.0.1	N/A	
SUN/STK	9740	SCSI ACSLs	DLT4000	DLT III	2.00.02	N/A	
			DLT7000	DLT IV			
			9840	SUN STK			
			9940	SUN STK			
SUN/STK	L500 SL500	SCSI FC	HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	1.00.7 (5.46.00) OR ACSLs 7.1	S*	* For Non-ACSLs Environments ** Minimum Firmware Requirement: 1126 (7381)
			IBM Ultrium 2 IBM 3580-TD2				
			HP Ultrium 9xx HP Ultrium 3-SCSI				
			IBM Ultrium 3 IBM 3580-TD3	LTO-3			
			IBM Ultrium 4 IBM 3580-TD4**	LTO-4			
			HP Ultrium 18xx HP Ultrium 4-SCSI**	LTO-4			
			9840B	SUN STK			
SUN/STK	SL8500	Requires ACSLS APM	9840C	SUN STK	ACSLs 7.1	N/A	
			9940B	SUN STK			
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2			
			IBM Ultrium 2 IBM 3580-TD2				
			IBM Ultrium 3 IBM 3580-TD3				
			HP Ultrium 18xx HP Ultrium 4-SCSI	LTO-4			
			IBM Ultrium 4 IBM 3580-TD4	LTO-4			
			9840	SUN STK			
			9940B	SUN STK			
SUN/STK	L5500	Requires ACSLS APM	IBM Ultrium 1 IBM 3580-TD1	LTO-1	ACSLs 6.0.1	N/A	
						N/A	
						N/A	

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1		N/A	
SUN/STK	L700	SCSI FC ACSL5	9840	SUN STK	3.06.00 03.15.02**	S*	See the STK L180 Application Notes for special support conditions and cleaning details. * For Non-ACSL5 Environments Only ** Minimum Firmware Requirement: 1126 (7381)
			9940B	SUN STK			
			9840C	SUN STK		S*	
			IBM Ultrium 1 IBM 3580-TD1	LTO-1		B*	
			HP Ultrium 2xx HP Ultrium 1-SCSI				
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2		B*	
			IBM Ultrium 2 IBM 3580-TD2				
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3		G*	
			IBM Ultrium 3 IBM 3580-TD3				
			IBM Ultrium 4 / IBM 3580-TD4**	LTO-4		B*	
			HP Ultrium 18xx HP Ultrium 4-SCSI**	LTO-4		S*	
			DLT7000	DLT IV		S*	
			DLT8000	DLT IV		S*	
			SDLT320	SDLT I		N/A	
SDLT600	SDLT II	G					
SUN/STK	L1400M	SCSI FC	9840	SUN STK	3.07.00 03.15.02**	S*	Note: Uses L180/L700 Template. See the STK L180 Application Notes for special support conditions and cleaning details. * For Non-ACSL5 Environments Only
			9940B	SUN STK			
			9840C	SUN STK		S*	
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1		B*	
			IBM Ultrium 1 IBM 3580-TD1				
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2		B*	
			IBM Ultrium 2 IBM 3580-TD2				
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3		G*	
			IBM Ultrium 3 IBM 3580-TD3				
			HP Ultrium 18xx HP Ultrium 4-SCSI**	LTO-4		S*	
			IBM Ultrium 4 IBM 3580-TD4**	LTO-4		B*	
			DLT7000	DLT IV		S*	
			DLT8000	DLT IV		S*	
			SDLT320	SDLT I		G*	
SDLT600	SDLT II	G*					
		SCSI	9840	SUN STK	2.00.00	S*	Note: Uses L180/L700 Template. See the STK L180 Application Notes for special support conditions and cleaning details. * For Non-ACSL5 Environments Only
			9840C	SUN STK	3.06.00	S*	
			9940B	SUN STK	0001		
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	0001	B*	
			IBM Ultrium 1 IBM 3580-TD1				
HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	0213	B*				

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:	
SUN/STK	L180	SCSI FC ACSLs	IBM Ultrium 2 IBM 3580-TD2	LTO-2	0215	B*	Note: Uses L180/L700 Template. See the STK L180 Application Notes for special support conditions and cleaning details. * For Non-ACSLs Environments Only	
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	0215	G*		
			IBM Ultrium 3 IBM 3580-TD3					
			HP Ultrium 18xx HP Ultrium 4-SCSI**	LTO-4		S*		
			IBM Ultrium 4 IBM 3580-TD4**	LTO-4	03.15.02	B*		
			DLT7000	DLT IV	0001	S*		
			DLT8000	DLT IV	0001	S*		
			SDLT320	SDLT I	0001	G*		
			SDLT600	SDLT II	0001	G*		
			SUN/STK	L80	SCSI	HP Ultrium 2xx HP Ultrium 1-SCSI		LTO-1
IBM Ultrium 1 IBM 3580-TD1								
HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	0213				B*		
IBM Ultrium 2 IBM 3580-TD2								
HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	0215				G*		
IBM Ultrium 3 IBM 3580-TD3								
HP Ultrium 18xx HP Ultrium 4-SCSI**	LTO-4					S*		
IBM Ultrium 4 IBM 3580-TD4**	LTO-4	03.15.02				B*		
DLT7000	DLT IV	0001				S*		
DLT8000	DLT IV	1.20.00				S*		
SUN/STK	L40	SCSI	HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	0001	B*	Note: Uses L180/L700 Template. See the STK L180 Application Notes for special support conditions and cleaning details. * For Non-ACSLs Environments Only	
			IBM Ultrium 1 IBM 3580-TD1					
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	0213	B*		
			IBM Ultrium 2 IBM 3580-TD2					
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	0215	G*		
			IBM Ultrium 3 IBM 3580-TD3					
			IBM Ultrium 4 IBM 3580-TD4**	LTO-4	03.15.02	B*		
			HP Ultrium 18xx HP Ultrium 4-SCSI**	LTO-4		S*		
			DLT7000	DLT IV	0001	S*		
			DLT8000	DLT IV	1.20.00	S*		
SUN/STK	L20	SCSI	HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	0001	B*	Note: Uses L180/L700 Template. See the STK L180 Application Notes for special support conditions and cleaning details. * For Non-ACSLs Environments Only	
			IBM Ultrium 1 IBM 3580-TD1					
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	0213	B*		
			IBM Ultrium 2 IBM 3580-TD2					
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	0215	G*		
			IBM Ultrium 3 IBM 3580-TD3					
			IBM Ultrium 4 IBM 3580-TD4**	LTO-4	03.15.02	B*		

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
			HP Ultrium 18xx HP Ultrium 4-SCSI**	LTO-4		S*	
			DLT8000	DLT IV	0001	S*	
			SDLT320	SDLT I	0001		
SUN/STK	SL24	SCSI FC*	HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	C.20	G●	● Read HP MSL2024 Application Note for cleaning details
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	C.20	G●	
SUN/STK	SL48	SCSI FC*	HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	E.60	G●	● Read HP MSL4048 Application Note for cleaning details
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3	E.60	G●	
SUN/STK	Virtual Tape Library	FC	Various See App Notes	Various See App Notes	3.1 Build 1070-012	N/A	The Virtual Tape Library is an appliance emulating virtual tape libraries with a variety of supported drives and media types. See The FalconStor IPStor Virtual Tape Library Application Notes for library and drive emulation modes supported.
SUN/STK	Virtual Tape Library PLUS	FC	Various See App Notes	Various See App Notes	v4.0 (Build 1323)	N/A	The Virtual Tape Library is an appliance emulating virtual tape libraries with a variety of supported drives and media types. See The SUN VTL Plus Tape Library Application Notes for library and drive emulation modes supported.
SUN/STK	C2	SCSI	SDLT600	SDLT II	000C	G	Read Application Notes for special support conditions and cleaning details. Use Quantum SuperLoader 3 template or Sun C2 template available from Sun.
			Certance Ultrium 2	LTO-2		G	
			Certance Ultrium 3	LTO-3		G	
			SDLT600	SDLT II		G	
SUN/STK	C4 / C10	SCSI FC	Certance Ultrium 2	LTO-2	V3.0 (0003)	G	Read Application Notes for special support conditions and cleaning details. Use Quantum PX500 template or Sun C4/C10 template available from Sun.
			Certance Ultrium 3	LTO-3		G	
			SDLT600	SDLT II		G	
			SDLT320	SDLT I		G	
SUN/STK	L8	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	F10r		Read Application Note for SDLT 320 Cleaning details
			IBM Ultrium 1 IBM 3580-TD1	LTO-1			
SUN/STK	L25	SCSI	HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	2.02		Use M1500 Template or the Sun L25 Template available from Sun
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3			
SUN/STK	L100	SCSI	SDLT320	SDLT I	2.02		Use M1500 Template
			SDLT600	SDLT II			
			HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1			
			HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2			
SUN / STK	L1000	SCSI	DLT7000	DLT IV	245F		
			DLT8000	DLT IV	0100		
* NOTE1: FC support requires optional Modular Data Router **NOTE2: Virtual Tape Drives Supported							
Tandberg / Exabyte							
Tandberg / Exabyte	SLR Autoloader	SCSI	SLR7	SLR	v2.07		
		SCSI	SLR60	SLR	v2.07		
		SCSI	SLR100	SLR	v2.07		
Tandberg / Exabyte	ThinStor Autoloader	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	0002		Use NEC LL0101H Template. See App Notes for cleaning details.
			IBM Ultrium 2 IBM 3580-TD2	LTO-2	0002	S	
			IBM Ultrium 3 IBM 3580-TD3	LTO-3	0004	B	
Tandberg / Exabyte	DLT Autoloader	SCSI	DLT8000	DLT IV	0002	S	
Tandberg / Exabyte	SDLT Autoloader	SCSI	SDLT220	SDLT I	0001	N/A	
Tandberg / Exabyte	1U StorageLoader	SCSI	Tandberg 220LTO	LTO-1	0140		
			Tandberg 420LTO	LTO-2			
			HP Ultrium 9xx HP Ultrium 3-SCSI	LTO-3			
			DLT VS160	DLT VS1			
Tandberg / Exabyte	StorageLoader LTO 2U	SCSI	HP Ultrium 4xx HP Ultrium 2-SCSI	LTO-2	C113	G	

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
Tandberg / Exabyte	ThinStorPlus 2U Autoloader	SCSI	HP Ultrium 2xx HP Ultrium 1-SCSI	LTO-1	1.20 / 1.30		
			IBM Ultrium 2 IBM 3580-TD2	LTO-2			
			IBM Ultrium 3 IBM 3580-TD3	LTO-3			
			SDLT320	SDLT I			
			SDLT600	SDLT II			
Tandberg / Exabyte	ATL M1500	SCSI	DLT8000	DLT IV	2.02	S	
			SDLT320	SDLT I	2.02		
			SDLT600	SDLT II	0a0a		
			HP Ultrium 2xx HP Ultrium 2-SCSI	LTO-1	2.02		
			DLT8000	DLT IV	2.02	S	
Tandberg / Exabyte	ATL M2500	SCSI	SDLT320	SDLT I	2.02		
			HP Ultrium 2xx HP Ultrium 2-SCSI	LTO-1	2.02		
			IBM Ultrium 2 IBM 3580-TD2	LTO-2	109D / 227D		
IBM Ultrium 3 IBM 3580-TD3	LTO-3						
Tandberg / Exabyte	T40	SCSI	IBM Ultrium 3 IBM 3580-TD3	LTO-3	2.60		See App Notes for Cleaning Tape Support
		SCSI	IBM Ultrium 4 IBM 3580-TD4	LTO-4	74H6		See App Notes for Cleaning Tape Support
Tandberg / Exabyte	TDS 1210	SCSI	SLR100	SLR	2.10B		
Tandberg / Exabyte	TDS 1420	SCSI	SLR100	SLR	2.10		
Tandberg / Exabyte	TDS 1440	SCSI	SLR100	SLR	2.10		
Tandberg / Exabyte	440 / 480	SCSI	820	8MM	TBD	S	
			Mammoth	8MM	TBD	S	
Tandberg / Exabyte	EZ17	SCSI	Mammoth	8MM	TBD	S	
			Mammoth-LT	8MM	TBD	S	Read Application Note for Mammoth-2 cleaning details
			Mammoth-2	8MM	1.7.4	S	
			Mammoth	8MM	TBD	S	
Tandberg / Exabyte	X80	SCSI	Mammoth-2	8MM	2.6.1	S	Read Application Note for Mammoth-2 cleaning details
			Mammoth	8MM	TBD	S	
Tandberg / Exabyte	X200	SCSI	Mammoth-2	8MM	TBD	S	Read Application Note for Mammoth-2 cleaning details
			Mammoth	8MM	TBD	S	
Tandberg / Exabyte	430M	SCSI	Mammoth	8MM	TBD	S	Read Application Note for Mammoth-2 cleaning details
			Mammoth-2	8MM	2.4.5	S	
Tandberg / Exabyte	215M	SCSI	Mammoth	8MM	TBD	S	Read Application Note for Mammoth-2 cleaning details
			Mammoth-2	8MM	TBD	S	
Tandberg / Exabyte	Magnum 1x7	SCSI	IBM Ultrium 2 IBM 3580-TD2	LTO-1	B003	S	
			IBM Ultrium 2 IBM 3580-TD2	LTO-2	B006		
Tandberg / Exabyte	Magnum 8x143 (Magnum20)	SCSI FC	IBM Ultrium 1 IBM 3580-TD1	LTO-1	2.0.7	S	
			IBM Ultrium 2 IBM 3580-TD2	LTO-2	2.0.7	S	
			IBM Ultrium 3 IBM 3580-TD3	LTO-3	2.0.7		
Tandberg / Exabyte	221L	SCSI FC	IBM Ultrium 4 IBM 3580-TD4	LTO-4	2.4.5	S	
			IBM Ultrium 4 IBM 3580-TD4	LTO-4		S	
			IBM Ultrium 4 IBM 3580-TD4	LTO-4	3.6.2		FC Firmware minimum is 11.6.1
Tandberg / Exabyte	224	SCSI FC	IBM Ultrium 2 IBM 3580-TD2	LTO-2	C113		Cleaning Tapes are not supported by the NetVault Software at this time, please refer to application notes for details.
			IBM Ultrium 4 IBM 3580-TD4	LTO-4	74H6		
			IBM Ultrium 2 IBM 3580-TD2	LTO-2	0009		
IBM Ultrium 3 IBM 3580-TD3	LTO-3			Cleaning Tapes are not supported by the NetVault Software at this time, please refer to application notes for details.			

Vendor	Model	Interface Tested	Drive Model(s)	Primary Media Format	Minimum Library Firmware Level OR Minimum Software Level	Cleaning Tape Support	Notes:
			IBM Ultrium 4 IBM 3580-TD4	LTO-4	74H6		
Tandberg / Exabyte	110L	SCSI	IBM Ultrium 1 IBM 3580-TD1	LTO-1	2.18.2	S	
			IBM Ultrium 2 IBM 3580-TD2	LTO-2		S	
			IBM Ultrium 3 IBM 3580-TD3	LTO-3	3.6.2		
Tandberg / Exabyte	230D	SCSI	DLT7000	DLT IV	2.6.3	S	
Tandberg / Exabyte	AutoPak 1x10	SCSI	VXA-1	VXA	E35r		
			VXA-2	VXA	E35r	S	
Tandberg / Exabyte	VXA-172 PacketLoader 1x10 1U	SCSI	VXA-172	VXA	TBD		
Tandberg / Exabyte	VXA-2 PacketLoader 1x10 1U	SCSI	VXA-2	VXA	A102	S	
Tandberg / Exabyte	VXA-2 PacketLoader 10	Firewire 800	VXA-2	VXA	A108	S	Supported with NetVault 7.1.1 (and higher) for Mac OSX only. Requires Mac OSX Support Pack 2. See Application Notes for additional information before installing.
Tandberg / Exabyte	VXA-320 PacketLoader 1x10 1U	SCSI	VXA-320	VXA	A102		
Tandberg / Exabyte	AutoPak 1x15	SCSI	VXA-1	VXA	2848	S	
Tandberg / Exabyte	AutoPak 1x7	SCSI	VXA-2	VXA	1.11.2	S	